
How To Use A Plasma Cutter

*How To Use A Plasma
Cutter*

*Downloaded from
www.everybodystreet.com
by Huang & Malik*

INTRODUCTION

If you have ever watched a skilled fabricator slice through thick steel with what looks like a magical blue flame, you have witnessed the raw power of a plasma cutter. For many DIY enthusiasts, welders, and metalworkers, the plasma cutter is a game-changing tool that delivers fast, clean cuts on electrically conductive metals. But mastering this tool requires more than just pulling the trigger. Knowing **how to use a plasma cutter** safely and effectively can transform your metalworking projects from frustrating to flawless. This comprehensive guide walks you through everything you need to know, from safety essentials and machine setup to advanced cutting techniques and maintenance. Whether you are a beginner or a seasoned professional looking to refine your skills, this article will give you the confidence to make precise cuts on steel, stainless steel, aluminum, and other metals.

UNDERSTANDING PLASMA CUTTING BASICS

Before diving into the step-by-step process of **how to use a plasma cutter**, it helps to understand what makes the tool work. A plasma cutter uses a high-velocity jet of ionized gas (plasma) that is heated to extreme temperatures – often over 20,000°C (36,000°F). This plasma arc melts the

metal, while the gas flow blows away the molten material, creating a clean kerf. The process is faster than oxy-fuel cutting and can handle a wider range of materials and thicknesses.

Key components of a plasma cutting system:

- **Power supply:** Converts incoming electrical power into the correct voltage and current for the cutting arc.
- **Torch:** Houses the electrode and nozzle; the user holds this to direct the arc.
- **Electrode and nozzle:** Consumable parts that wear over time; they shape and concentrate the plasma stream.
- **Air compressor or gas source:** Provides compressed air (or other gases like nitrogen) to create the plasma and cool the torch.
- **Ground cable and clamp:** Completes the electrical circuit and must be securely attached to the workpiece.

Plasma cutters range from small 110V units ideal for thin metal up to industrial CNC machines that cut thick plate. The fundamental operating principles remain the same, regardless of size.

SAFETY FIRST: ESSENTIAL PRECAUTIONS FOR PLASMA CUTTING

Safety is non-negotiable when learning **how to use a plasma cutter**. The arc is extremely bright, the metal is molten,

and the noise can damage hearing. Follow these safety guidelines every time you cut.

Personal Protective Equipment (PPE)

- **Auto-darkening welding helmet** with a shade rating of at least 9-12 for plasma cutting. The brightness can cause flash burns if you look at the arc without protection.
- **Safety glasses** under the helmet for side impact protection.
- **Flame-resistant clothing** (cotton or leather) – avoid synthetic fabrics that can melt to your skin.
- **Welding gloves** – heat-resistant and insulated to protect from sparks and hot metal.
- **Ear protection** – the noise from the plasma arc can exceed 100 dB.
- **Steel-toe boots** to protect against dropped metal.

Work Area Safety

- Ensure adequate ventilation – plasma cutting produces fumes (especially when cutting galvanized or painted metal) that can be toxic. Use local exhaust or a respirator if needed.
- Keep a fire extinguisher rated for electrical and metal fires nearby.
- Clear the area of flammable materials (paper, wood, solvents, oil).
- Use a cutting table with a grounded metal surface or a fire-

resistant bench.

- Never cut in wet conditions – risk of electric shock.

Electrical Safety

- Check that the plasma cutter's power cord and plug are in good condition.
- Ground the workpiece with the clamp as close to the cut as possible to ensure a stable arc and avoid stray currents.
- When using a handheld plasma cutter, keep the torch cable away from sharp edges that could damage insulation.

SETTING UP YOUR PLASMA CUTTER FOR THE FIRST CUT

Proper setup is a critical part of **how to use a plasma cutter** effectively. Follow these steps to get ready.

Step 1: Connect the Air Supply

Most handheld plasma cutters require compressed air. Connect your air compressor to the cutter's air inlet using the appropriate hose. Set the regulator according to the manufacturer's recommended pressure (commonly 60-80 PSI). Moisture in the air can damage consumables, so if possible use a dryer or a water separator.

Step 2: Install

Consumables

Check the torch. Install a new electrode and nozzle appropriate for the material thickness. Make sure they are tight but not over-torqued. Some units also require a swirl ring – follow your manual.

Step 3: Attach the Ground Clamp

Clean the area on the workpiece where you will attach the ground clamp. Rust, paint, or scale can cause poor contact and arc instability. Clamp it directly to the metal, as close to the cutting area as possible. If you are cutting a piece that is isolated, place it on a steel table and clamp the table.

Step 4: Set Amperage and Mode

Adjust the amperage based on material thickness. Many units have a chart on the side. For example, cutting 1/4-inch mild steel might require 30-40 amps, while 1/2-inch might need 60 amps. Some units have a "cut" and "gouge" mode – for cutting, select the normal mode.

Step 5: Perform

a Test

Before cutting your final piece, do a quick test on scrap metal to verify that the arc starts cleanly and cuts smoothly. Adjust settings if you see a lot of dross (re-solidified metal) or if the arc seems weak.

STEP-BY-STEP: HOW TO USE A PLASMA CUTTER TO CUT METAL

Now let's get into the actual cutting process. Whether you are cutting a straight line, a circle, or following a template, these steps will guide you.

Positioning the Torch

Hold the torch perpendicular to the workpiece, or tilt it slightly in the direction of travel (drag-cutting). Many beginners find it easiest to start with the nozzle resting lightly on the metal (for drag-cut tips) or held at a 90-degree angle with a slight gap. If using a drag tip, you can slide the nozzle directly on the metal; this helps maintain the correct standoff distance.

Initiating the Plasma Arc

Press the trigger. You will hear a high-pitched hiss and see a pilot arc (a small spark) that then transfers to the workpiece. Do not press the trigger until you are ready to start the cut, because the pilot arc wears consumables. Once the main cutting arc ignites, you will see a bright stream of plasma and molten metal spraying out from the bottom.

Moving the Torch

Start moving the torch at a steady, consistent speed. If you move too slowly, you get excessive dross and a wider kerf. Too fast, and the arc may not penetrate fully. You should see a clean stream of sparks coming from the underside of the metal. Listen to the sound: a smooth, consistent hiss indicates a good cut. If you hear sputtering, adjust your speed or amperage.

For straight cuts: Use a straightedge guide or a metal ruler. Keep the torch perpendicular and guide your hand along the edge. If your cutter has a built-in circle cutting guide, use it for arcs.

For thin metal (under 1/8 inch): Lower amperage and faster travel speed. You may need to "drag" the tip to maintain arc stability.

For thick metal (over 1/2 inch): Increase amperage and use a slower, steady hand. Consider making two passes if needed (rough cut then trim). Keep the torch slightly angled to improve cut quality.

Ending the Cut

When you reach the end of the cut, release the trigger. The gas flow will continue for a second or two to cool the torch – do not set the torch down until the flow stops. Allow the cut piece to cool before handling. If you need to restart in the middle of a cut, you can press the trigger again, but be aware that restarting over an existing cut can cause arc instability.

COMMON CUTTING TECHNIQUES

AND TIPS

Mastering **how to use a plasma cutter** also involves learning different techniques for various situations.

Drag Cutting vs. Standoff Cutting

Most modern handheld plasma cutters support drag cutting, where the nozzle rests directly on the metal. This makes it easier to maintain consistent distance. For consumables that are not rated for drag cutting, you must hold a small gap (1/16 to 1/8 inch) using a standoff guide or your steady hand. Check your consumable packaging – drag tips have a flat or slightly recessed electrode.

Cutting Grates and Bars

When cutting expanded metal or grating, use a lower amperage and a faster travel speed to minimize melting of the cross members. You may need to angle the torch slightly to avoid excessive damage to the underlying bars.

Piercing Holes

To pierce metal (start a cut from the middle), angle the torch 45 degrees first to let the molten metal flow away from the nozzle. Slowly rotate to upright and then proceed. Always pierce away from yourself. For thicker metal, you may need to drill a small pilot hole first.

Removing Dross

Dross (hard slag) often forms on the bottom edge of the cut. It can be chipped off with a hammer or an angle grinder. Minimize dross by using the correct amperage and travel speed. If dross is excessive, check your consumable condition and air pressure.

CONSUMABLE CARE AND MAINTENANCE

To keep your plasma cutter performing well and to get the most out of your consumables, follow these maintenance tips.

- **Inspect consumables regularly.** Look for a worn electrode: a deep pit in the center means it's time to replace. A damaged nozzle (oval or hole) will ruin cut quality.
- **Replace as a set.** When you replace the electrode, also replace the nozzle and swirl ring to ensure proper gas flow.
- **Keep air dry.** Moisture in the air accelerates consumable wear. Drain your compressor tank daily and use an inline filter.
- **Clean the torch.** Wipe off any spatter or dirt from the exterior and inside the torch head.
- **Store the torch properly.** Do not coil the cable tightly; hang it loosely to avoid damaging the wires inside.

For industrial or frequent use, keep a log of hours per consumable set. Typically, a set may last 30 minutes to 2 hours of actual arc time.

TROUBLESHOOTING COMMON

ISSUES

Even experienced operators face problems. Here are quick fixes for common scenarios when learning **how to use a plasma cutter**.

Arc won't start

- Check that the ground clamp is properly attached and the workpiece is clean metal.
- Verify that your air pressure is within the required range.
- Look for worn or damaged consumables – replace if needed.
- Ensure the torch trigger is functioning (some units have a safety lock).

Cuts are uneven or rough

- Reduce travel speed or increase amperage.
- Check for a worn nozzle or misaligned electrode.
- Make sure the torch is perpendicular to the surface.
- Clean the metal surface of paint or rust.

High dross buildup

- Increase travel speed – dross often results from moving too slowly.
- Double-check amperage settings – too high can cause excess dross.
- Replace worn consumables.

Consumables wearing out too fast