

---

# 532 Ford Square Baler

---

Downloaded from  
[www.everybodystreet.com](http://www.everybodystreet.com)  
532 Ford Square Baler by Nicholson & Cochran

---

## THE 532 FORD SQUARE BALER: A COMPREHENSIVE GUIDE TO A CLASSIC HAY MAKING MACHINE

---

In the world of hay and forage equipment, few names carry the weight of tradition and reliability that Ford does. Among the many implements that have dotted the agricultural landscape, the **532 Ford Square Baler** stands out as a durable, efficient machine that helped countless farmers transition from loose

hay to neatly tied bales. Whether you are a collector, a small-scale farmer, or someone curious about vintage equipment, understanding the 532 model offers valuable insight into the evolution of baling technology. In this guide, we explore everything from its history and design to its operational quirks and modern relevance.

## History and

# Development of the Ford 532 Baler

Ford entered the baler market in the mid-20th century, aiming to provide affordable, robust equipment for the family farm. The **532 Ford Square Baler** was introduced during the 1960s and quickly became a workhorse model. Unlike some of its competitors, the 532 was designed to pair seamlessly with Ford tractors of the era, such as the 4000 or 5000 series, but it could also be pulled by other makes with the proper PTO speed. Its square bale production

allowed farmers to handle hay more efficiently than with loose stacking, reducing labor and storage losses.

The baler was built with a simple, mechanical system — no complex hydraulics or electronics — which made it easy to repair in the field. This durability is a major reason why many 532 models are still operating today, over fifty years after they rolled off the assembly line.

## Key Features of the

# 532 Ford Square Baler

When evaluating the **532 Ford Square Baler**, several features stand out that contributed to its popularity:

- **PTO-Driven Flywheel:** A heavy flywheel provides momentum to keep the plunger moving through dense hay, reducing the risk of plugging.
- **Twine Tying Mechanism:** The automatic twine knotter is one of the most critical components. The 532 uses a

double-knotter system that ties two strands around each bale, ensuring secure and consistent bale shape.

- **Pickup Reel:** A wide pickup with spring-tined teeth lifts the windrow into the feed chamber.

The reel is adjustable to match ground speed and crop conditions.

- **Shear Bolt Protection:** A safety shear bolt on the flywheel prevents major damage if a foreign object enters the baler. This simple but effective design saved many farmers costly repairs.

- **Bale Density**

**Control:** An adjustable tension mechanism allows the operator to set how tight the bales are compressed, from soft for easy handling to dense for better storage.

These features, combined with straightforward maintenance, made the 532 a trusted partner for haying seasons across North America and beyond.

## Operating the 532

# Ford Square Baler: Tips and Best Practices

Running a **532 Ford Square Baler** successfully requires understanding a few nuances. First, proper PTO speed is essential — typically 540 rpm at the baler input. Running too slow leads to poor bale density and missed ties; too fast can stress the driveline and cause overheating of the knotters.

Before each use, inspect the twine discs

and needles. The 532's knotter mechanism is sensitive to twine quality; using old or brittle twine can cause jams. Lubricate all grease fittings daily, especially around the knotter assembly and plunger guides. Many farmers also recommend checking the shear bolt condition — carry spare bolts in your tractor cab to avoid downtime.

Windrow management is another key factor. The pickup works best with uniform, not too thick, windrows. If the windrow is heavy, slow down the ground speed to give the plunger time to compress the hay properly. The 532 can handle a variety of crops — from alfalfa and timothy to straw and corn stalks — but adjustments to the

knife and shear bar clearances may be needed for different stem thicknesses.

## Maintenance and Restoration of the 532 Square Baler

One reason the **532 Ford Square Baler** remains a favorite among vintage equipment enthusiasts is its repairability. Parts are still available through aftermarket suppliers, and many components are shared with other Ford/New

Holland balers from the same era. Common wear items include pickup teeth, knitter parts, and the bale chamber floor.

For restoration, start with the driveline: replace the universal joints and check the flywheel bearings. The plunger channel should be inspected for wear — if the plunger rocks excessively, bales will be crooked and tying becomes erratic. The knotters should be disassembled, cleaned, and adjusted according to the service manual. A well-restored 532 can produce bales that rival modern machines in shape and density, though at a slower pace.

Owners often note that the 532 runs cooler than some later balers because of its open design and mechanical

simplicity. It is also lighter in weight, making it easier to tow with smaller tractors.

## Comparing the 532 to Other Ford Balers

Ford produced several square baler models, including the 530, 531, and the later 534. The **532 Ford Square Baler** sits in the middle of this lineage. Compared to the 530, it has a wider pickup and an improved knotter design. The 531 introduced some refinements, but the 532 is often considered the most balanced model — not as

complex as the later 534, but more capable than the 530.

When compared to modern square balers from New Holland (which succeeded Ford's tractor business), the 532 is significantly less automated. There is no hydraulic bale tension, no net wrap, and no in-cab monitor. However, for farmers who enjoy hands-on work and want a machine that can be repaired with basic tools, the 532 remains a viable option for small acreages and custom baling.

## Where to Find a 532 Ford

## Square Baler Today

Despite its age, the **532 Ford Square Baler** appears frequently at farm auctions, on online classifieds, and in vintage equipment forums. Prices vary widely based on condition — a non-running project machine can cost a few hundred dollars, while a completely restored example with new knotters and paint can sell for several thousand. Before purchasing, check for cracks in the main frame, excessive wear on the flywheel bearing surfaces, and the condition of the pickup reel. Also, verify that

the twine tension springs are intact and that the knotter cams are not worn.

Many tractor clubs and online communities (such as Yesterday's Tractors forums) offer advice on finding parts and troubleshooting. The Ford 532 baler has a dedicated following, and most owners are happy to share their experiences.

## Conclusion: The Enduring Legacy of the 532 Ford

# Square Baler

In an age of high-tech combines and GPS-guided tractors, the **532 Ford Square Baler** stands as a testament to an era when simple, rugged engineering got the job done. It offers a tangible connection to agricultural history while still being a functional tool for those willing to put in some maintenance effort. Whether you are looking to bale hay for a few horses or simply want to appreciate the craftsmanship of mid-century farm machinery, the 532 is a rewarding machine to own. Its straightforward design, strong construction, and enduring parts

availability ensure that tie bales for years to  
the 532 will continue to come — one perfect  
square at a time.